


Explanation

- Management, road-related landslides
- Management, road-related landslides too small to delineate at this scale
- Management, non-road-related landslides
- Management, non-road-related landslides too small to delineate at this scale
- Watershed / Property Boundary
- Subbasin Boundary
- Road
- Class I Stream
- Class II Stream

3



Contour Interval = 200 Feet



Mattole River Watershed Analysis
Humboldt Redwood Company
Humboldt County, California

Road-Related & Non-Road-Related Landslides 1988 - 2003
Plate 7